



FIG. 4. PV-SEM images fractographs of fracture surfaces of tested samples after impact tests at room temperature and sub-zero temperature (a) AA5083 (b) Modified AA5083 alloys